Report Number: Passadiço - 06





## **Construction Progress Report**

Monthly Period Reporting

Start: Thursday, 01 September 2022 End: Friday, 30 September 2022

Builder

NS Reformas, Construccion Y Trading S.L.U

## **Current Process**

1. Build capping beam

**Description of work** 

- 2. Execute foundation construction
- 3. Start to demolish the 1st floor

## **Process Photos**



Report Number: Passadiço - 06









Report Number: Passadiço - 06





As mentioned in the August construction report, the builders were working on the capping beam. In September, they finished assembling the steel structure and wooded mould, pouring concrete into it to build the capping beam of external walls on the top of the existing building, in order to strengthen the outside wall structure and avoid future collapse.



Report Number: Passadiço - 06







Report Number: Passadiço - 06







At the end of August, the builders finished a general excavation reaching the lowest level of this building. In September, they continued excavating the foundation foot, in order to reinforce the building foundation for the new structure. Following the steps, a thin layer of concrete was applied as a basement of the foundation, and then the reinforced steel bars were installed.

In addition, the builders started to demolish the 1st floor walls and slabs at the end of September.