



Report Number: Laurel - 08

## **Construction Progress Report**

Monthly Period Reporting	Start: Saturday, 01 October 2022 End: Monday, 31 October 2022
Builder	LADRILLO S.A - Construção, Remodelações e Projecto

## **Current Process**


- 1. Finish building capping beam
- 2. Work on concrete structure
- **Description of work** 3. Remove plaster from the existing walls
  - 4. Excavation
  - 5. Build exterior walls






Report Number: Laurel - 08

## **Process Photos**



























Report Number: Laurel - 08



In October, the builders finished assembling a steel structure and wooden mode, poured concret to form a capping beam which tiles all the piling together to create the foundation for the next step. They continued installing the columns and bricks on the beam to build concrete structure from the 2nd floor to the 3rd floor.









Report Number: Laurel - 08

Meanwhile, the builders started to remove those existing plasters from the facade walls, and then filled the gaps and apply reinforcement plaster on it again later on.







Report Number: Laurel - 08



Following the work plan, the builder was doing an excavation for the footing of the building foundation, to build a steel structure to reinforce it in the future.





Report Number: Laurel - 08



The exterior wall on the 2nd floor was finished in October. At the same time, the builders extended the existing walls attaching with the next building with bricks.