

Report Number: Freiras - 22

Construction Progress Report

Monthly Period Reporting	Start: Wednesday, 01 May 2024	End: Friday, 31 May 2024
Builder	LADRILLO S.A - Construção, Remodelações e Projecto	

1. Assemble roof steel structure

Current Process

Description of work

2. Demolition


Process Photos












Project: Largo Rodrigues de Freitas no 4 e 5 e Beco da Lage no 4, 1100-455 Lisboa Report Number: Freiras - 22











Report Number: Freiras - 22




As mentioned in the previous report, the builders began assembling the steel structure for the roof in April. This month, they concentrated on completing this assembly, successfully installing the steel structure frame on the roof and constructing the surrounding walls along the roof edge.





Project: Largo Rodrigues de Freitas no 4 e 5 e Beco da Lage no 4, 1100-455 LisboaReport Number: Freiras - 22





Report Number: Freiras - 22



As emphasized in previous reports, our FGI project manager and engineer are meticulously focused on ensuring the structural integrity and stability of this aging building. After stablizing the above floor structure, the builders started to demolish the remaining 1st-floor pavement and the existing ground-floor walls at the end of May.