Report Number: Laurel - 27



Construction Progress Report

Monthly Period

Reporting

Start: Saturday, 01 June 2024 End: Sunday, 30 June 2024

Builder LADRILLO S.A - Construção, Remodelações e Projecto

Current Process

1. Zinc cladding

2. Insulation placing

Description of work

- 3. Building infrastructure work
- 4. Sewage connection to the city system
- 5. Screeding on the ground floor

Process Photos















Report Number: Laurel - 27






In June, the builders progressed with zinc cladding and roof tiling on the street-facing side, as well as placing insulation on the facade. In addition, they finished painting the facade that faces the garden.






















Report Number: Laurel - 27





Following the work completed in May, the constructors continued placing insulation within the interior walls of the apartments on the 1st floor, progressing subsequently to the 2nd-floor apartments.

Meanwhile, they advanced with the installation of a water piping system of the whole building, and successfully completed the leakage test. Additionally, they finished the AV sytem infrastructure installation.

Those customized windows have been produced and are ready in the workshop. They will be delivered and installed in July.



















Report Number: Laurel - 27



After the conduction of the water piping and sewage drainage system installation, and with an approved execution plan, the builders connected the building's sewage system to the public city sewage system.



Report Number: Laurel - 27





In June, the builders started to do screeding on the ground floor, placing a top layer of material laid over the concrete subfloor, to smooth the floor slab and assist in flattening.