Report Number: Passadiço - 27



Construction Progress Report

Monthly Period Reporting	Start: Saturday, 01 June 2024	End: Sunday, 30 June 2024
Builder	NS Reformas, Construccion Y Trading S.L.U	

Current Process

- 1. Install shower tray
- 2. Install windows and doors

Description of work

- 3. Roof tiling and assembling balustrade
- 4. Install rainwater drain pipes

Process Photos











Report Number: Passadiço - 27



As mentioned in the previous report, the builders finished applying waterproofing to the bathroom areas of the apartments and started tiling the floors and walls of the bathrooms. In June, they were tiling the bathrooms and installing shower trays for all apartments in the Passadiço project.





















Project: Rua do Passadiço 55, LisboaReport Number: Passadiço - 27






In May, the builders focused on repairing the existing stone window frames and preparing for window installation. The customized windows and doors were produced in the professional workshop. After receiving the delivery in June, the builders started installing them.











In June, the roof tiling was completed. Following this, the builders assemble the balustrade on the top floor roof. Meanwhile, they started installing storm and rain drain pipes along the facade walls.