Report Number: Passadiço - 27



Construction Progress Report

Monthly Period Reporting

Start: Monday, 01 July 2024 End: Wednesday, 31 July 2024

Builder NS Reformas, Construcción Y Trading S.L.U

Current Process

1. Place floor insulation

Description of work

2. Tile the balconies

3. Paint the walls

Process Photos








Report Number: Passadiço - 27






Following the work agenda, in July, the installation of flooring insulation commenced in July, starting from the 3rd floor and progressing downward to the ground floor. The insulation material used is cork, chosen for its soundproofing and thermal insulation properties. By the end of the month, the team had meticulously completed the installation on both the 2nd and 3rd floors.






















Report Number: Passadiço - 27






Meanwhile, the construction team was leveling the balcony floors in preparation for tiling. In July, after the tiles were delivered, they began the tiling process on the balconies.

















Report Number: Passadiço - 27



Painting work continued in July, with the construction team focusing on the interior walls of the apartments. Additionally, they began painting the facade in beige, in accordance with the licensing plan.